Dart Aerospa	ace	Ltd
---------------------	-----	-----

W/O:			V	ORK ORDER CHAI	NGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									į	
										·
Part No	:	PAR #:	Fault Ca	tegory:	NCR:	Yes I	No DQ	A:	_ Date: _	
		esolution:	Disposition:			QA: N/C Closed:				· .
NCR:			WORK OR	DER NON-CONFOR	MANCE (NCR)	· · · · · ·		·
DATE	STEP	Description of NC		Corrective Action Section B		Verific		ation	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Section C	•	1 4 5	Chief Eng	QC Inspector
				•					i	

NOTE: Date & initial all entries

Work Order ID 57530

April 8, 2010 8:13:17 AM

Required Date: 4/15/10



Page 2

Item ID:

D3536-35

Accept

Setup Start

Stop



Revision ID:

Item Name:

Gasket

4/08/10

Start Qty: 12.00

Req'd Qty: 12.00

Cust Item ID: Customer:

Reference:

Start Date:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start Run

Reject

Qty



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID**

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location

Memo

Set Up/ **Run Hours**

0.00

0.00

Draw Number

Draw Plan Code Rev.

Accept Qty

Reject Number

Insp. Stamp

11 130

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Dart Aerospace Ltd

	•									
W/O:			WC	ORK ORDER CHANG	GES					
DATE	STEP	PROCEDURE CHANGE			В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR: \	es N	lo DQ /	٨:	_ Date: _	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC	Corrective Action Section B			Ver			Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Section C	on C	Chief Eng	QC Inspector
										-
									į	
									,	

NOTE: Date & initial all entries

Picklist Print

April 8, 2010 8:13:16 AM

Work Order ID: 57530

Parent Item:

D3536-35

Parent Item Name:

Comments:

Gasket
IPP Rev:A

New Issue 07-02-14 JLM



Start Date: 4/08/10

Required Date: 4/15/10

Page 1

Start Qty: 12.00

Required Qty: 12.00

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
MNEO60S.063	-	Purchased	No			100	sf	378.0000	7.8278	- ··· · · · · · · · · · · · · · · · · ·		



NEOPRENE SHEET 0.063

Warehouse Loc Qty Loc Code

Location

Main Warehouse

MAT052

114176

378 378

114176



1R10-4-14

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No		PAR #:											
Reso		solution:	Dispositi	on:	QA: N/C (closed:		Date: _					
NCR:		,	WORK OR	DER NON-CONFORM	ANCE (NC	R)							
DATE	STEP	Description of NC		Corrective Action Section B			cation Approva	Approval	Approval				
	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section C		Chief Eng	QC Inspector				
		·		•									
			,										

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 57520)
Description: Gasket	Part Number: D3536-3	5
Inspection Dwg: D3536 Rev: A	Page 1 o	f 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
23.25	+/-0.030	56.26	80			
19.75	+/-0.030	14.75	×			
17.75	+/-0.030	17,75	×			
14.25	+/-0.030	14.75	7			
9.50	+/-0.030	9.50	Ľ			
4.75	+/-0.030	4.75	8			
2.00	+/-0.030	£001	8			
6.00	+/-0.030	6.00	7			
6.75	+/-0.030	6.75	×			
0.30	+/-0.030	.303	L			
0.30	+/-0.030	.304	X			
1.89	+/-0.030	1,899	X			
Ø0.19	+0.005/-0.001	GPI,	¥			
0.063	+/-0.010	,063	4			
	·		 			
	·					

Measured by:	HB.	Audited by:	Prototype Approval:	N/A
Date:	10-4-14	Date: (oloy)()	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.03.14	New Issue	KJ/JLM A	
	·			



Lean is...

- Promote customer-orientation rather than resource-orientation (produce for sales not for stock).
- A highly evolved method of managing an organization to improve the productivity, efficiency and quality of its products or services.
- Transforms how the company operates and how employees think about their work. Don't work harder but smarter by transferring your energy from the NVA to the VA activities.
- Has no end (there is no "done").

DATE 06.10.25 CHECKED B 3 D3536 GASKET DART **AEROSPACE**

HADLOCK,

SHEET

4 OF 6 SCALE 1:10

USA,


₹ C.

DETAIL A

#0.19 (TYP 3 PLS)

D3536-31 GASKET

22.50 19.00



D3536-33 GASKET

2.00 -

1.89

DOCUMENT

ឆ

Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

PURPOSE

S


COPIED

- 1) MATERIAL: BLACK NEOPRENE SHEET, 1/16 THICK, 60 DUROMETER (REF DART SPEC. M-NEO60-S.063)
- 2) FINISH: NONE

6.00 →

6.00

- PART IS SYMMETRICAL ABOUT & TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
 8) IDENTIFY WITH DART P/N USING A WHITE FINE POINT PERMANENT INK MARKER
- 7) SEE PAGE 6 FOR DETAILS AND SECTION



D3536-35 GASKET

W/O 57530



Lean Is...

"LEAN IS... A mindset, or way of thinking

- A commitment to achieve a totally waste-free operation focused on the customer's success
- Achieved by simplifying and continuously improving all processes and relationships in an environment of trust, respect and full employee involvement
- It is about people, simplicity, flow, visibility, partnerships and true value as perceived by the customer."

B

DRAWING NO.

SHEET 6 OF 6

SCALE 1:10

DART

AEROSPACE PORT HADLOCK,

USA,

NO.

07 02.12

06.10.25

GASKET



D3536-41 GASKET

ø0.19 (TYP 2 PLS)

27.98 25.08

18.50


15.00

2.00 ---

4.00 -

DETAIL A

- 1) MATERIAL: BLACK NEOPRENE SHEET, 1/16 THICK, 60 DUROMETER (REF DART SPEC. M-NEO60-S.063)
- 2) FINISH: NONE
- 3) PART IS SYMMETRICAL ABOUT ©
 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) IDENTIFY WITH DART P/N USING A WHITE FINE POINT PERMANENT INK MARKER



w/o 51530

1.88

3.90

DOCUMENT $\overline{\mathbf{v}}$ Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC. PURPOSE 윢 COPIED

HIS



Lean Is...

- "LEAN IS from an operations perspective... a system that cuts costs & inventories rapidly to free cash, which is critical in a slow economy. It also supports growth by improving productivity and quality, reducing lead times and freeing huge amounts of resources.
- Lean aims at reducing (if not eliminating) none value added activities in business processes.
- It's not a project.